

# Oil Field Environmental Incident Summary

**Incident:** 20150610135801      **Date/Time of Notice:** 06/10/2015 13:58

**Responsible Party:** HESS BAKKEN INVESTMENTS II, LLC

**Well Operator:** HESS BAKKEN INVESTMENTS II, LLC

**Well Name:** SC-HOVING 154-98-1003H-1

**Field Name:** TRUAX

**Well File #:** 22946

**Date Incident:** 6/9/2015

**Time Incident:** 02:30

**Facility ID Number:**

**County:** WILLIAMS

**Twp:** 154

**Rng:** 98

**Sec:** 10

**Qtr:**

**Location Description:** Fluid carry over to auxiliary flare caused a fire to start on the south side of location. Area affected by the fire is estimated at 210 ft. x 107 ft. south of location.

**Submitted By:** Troy Brunsell

**Received By:**

**Contact Person:** Jason Henry  
1501 MCKINNEY  
HOUSTON, TX 77010

**General Land Use:** Pasture

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:** 1 Mile

**Distance Nearest Water Well:** 1 Mile

**Type of Incident:** Fire

**Release Contained in Dike:** No

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0.8	Barrels			0	barrels

Brine

Other

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 1/13/2016

**Clean Up Concluded:** 6/23/2015

**Risk Evaluation:**

No immediate risk to report at this time.

**Areal Extent:**

Burned area is estimated at 210 ft. x 107 ft. south of location.

**Potential Environmental Impacts:**

Burned pasture grass on the south side of location in an estimated 210 ft. x 107ft. area.

**Action Taken or Planned:**

Production equipment was shut in, local Fire Dept. extinguished the fire.

**Wastes Disposal Location:** Approved waste disposal.

**Agencies Involved:** Local Fire Department

**Updates**

---

**Date:** 6/10/2015    **Status:** Reviewed - Follow-up Required

**Author:** Crowdus, Kory

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Fire impacted areas off location. Followup is required.

---

**Date:** 6/19/2015    **Status:** Inspection

**Author:** Kangas, Kathleen

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Burned pasture South of location, south of flare. Company estimate of 210 X 107 feet appears accurate. No oil seen standing, although burned area is blackened from fire. Follow-up on clean-up is needed.

---

**Date:** 8/1/2016      **Status:** No Further Action Requested

**Author:** Washek, Sandi

**Updated Oil Volume:** 0.80 barrels

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Arrived on site at 4:20 p.m. Weather was overcast, wind out of the SW at 10 mph, and temperature was 81 degrees F. The area impacted by the fire was located to the south of the pad and flare area. The area has re-vegetated. No additional follow-up needed.